

AC REPIERING RATE CARD

Sr no	Description	Service Charge
1	Non-Inverter PCB repaired	₹ 1,500
2	Inverter PCB repaired	₹ 4,000
3	Replace LVT	₹ 900 ₹499 (Labour)
4	Capacitor 2-5 mfd	₹ 250 ₹349 (Labour)
5	Capacitor 10-25 mfd	₹ 400 ₹349 (Labour)
6	Capacitor 35-50 mfd	₹ 400 ₹349 (Labour)
7	Capacitor 50-60 mfd	₹ 400 ₹349 (Labour)
8	Replace sensor	₹ 350 ₹499 (Labour)
9	Contactora replaced	₹ 500 ₹499 (Labour)
10	Contactora Daikin/ O-General	₹ 1,500 ₹449 (Labour)
11	Convert PCB with remote	₹ 1,500
Sr no	Description	Service Charge
1	Gas Charging	₹ 2,500
2	Flair nut replaced	₹ 150
3	Cooling Coil / Condenser Coil repair	₹ 0 ₹500 (Labour)
4	Copper Coil Condensor 1 ton Split	₹ 3,500
5	Copper Coil Condensor 1.5 ton Split	₹ 4,000
6	Copper Coil Condensor 2 ton Split	₹ 4,500
7	Service valve replaced (1 Pc)	₹ 400

Sr no	Description	Service Charge
1	Copper Cooling Coil (Split AC)	₹ 6,000
2	Capillary and filter replaced	₹ 350
3	Compressor 0.8-1 ton	₹ 6,500
4	Compressor 1.5 ton	₹ 7,500
5	Compressor 2 ton	₹ 9,200
6	Expansion valve replaced	₹ 1,200
7	Dead nut (1 pc)	₹ 50
8	U Band replaced (1 pc)	₹ 50
9	Pin Valve for window AC	₹ 50
	Copper Cooling Coil (Window AC)	₹ 4,500
Sr no	Description	Service Charge
1	Fan motor outdoor	₹ 1,800 ₹499 (Labour)
2	Blower motor replaced	₹ 2,200 ₹499 (Labour)
3	Blower replaced	₹ 1,100 ₹499 (Labour)
4	Replace Flap/Swing Motor	₹ 400 ₹499 (Labour)
Sr no	Description	Service Charge
1	Deep clean AC service (window)	₹ 599
2	Deep clean AC service (split)	₹ 699
3	Window AC Uninstallation	₹ 399
4	Split AC Uninstallation	₹ 649
5	Window AC Installation	₹ 799
6	Split AC Installation	₹ 1,999
7	1 meter copper pipe set (with insulation, wire)	₹ 900
8	Split AC Wall stand	₹ 550
9	Outdoor unit reinstalled	₹ 799

Sr no	Description	Service Charge
1	Indoor unit reinstalled	₹ 699
2	Drain pipe (1m)	₹ 100
3	Fastner complete set	₹ 200
4	Floor stand	₹ 750
5	Universal back plate	₹ 300
Sr no	Description	Service Charge
1	Water Leakage Repaired- Window AC	₹ 449
2	Water Leakage Repaired- Split AC	₹ 599
3		₹ 0
4	Adjust Grill Locks	₹349 (Labour)
5		₹ 0
6	Adjust pipe and tight compressor screw	₹349 (Labour)
7		₹ 100
8	Connector wires replaced (1m)	₹349 (Labour)
9		₹ 50
10	Tighten/ Replace Thimble	₹349 (Labour)
Sr no	Description	Service Charge
1	Water tray	₹ 500 ₹200 (Labour)
2	Sleeves (per piece)	₹ 50
3	Stabilizer repair	₹ 1,500
4		₹ 700
5	AC fan blade	₹499 (Labour)
6		₹ 1,500
7	Grill Cover	₹349 (Labour)
8		₹ 400
9	Swing blade replaced	₹349 (Labour)
10	Universal remote	₹ 800
11	Compressor grommets set	₹ 299
12	Rubber washer (1 pc)	₹ 50